

HUNTER VALLEY
OPERATIONS

**MONTHLY
ENVIRONMENTAL
MONITORING REPORT MAY
2024**

DOCUMENT NUMBER

HVOOC-1797567310-4964

STATUS

Approved

VERSION

1.0

EFFECTIVE

19/07/2024

REVIEW

[Planned Review Date]

OWNER

Superintendent - Environment and Community



1	Introduction.....	4
2	Air Quality.....	4
2.1	Meteorological Monitoring.....	4
2.1.1	Rainfall	4
2.1.2	Wind Speed and Direction	5
2.2	Depositional Dust.....	7
2.3	Suspended Particles.....	8
2.3.1	HVAS PM ₁₀ Results	8
2.3.2	HVAS PM _{2.5} Results	10
2.3.3	TSP Results	12
2.3.4	Real Time PM ₁₀ Results	13
2.3.5	Real Time Alarms for Air Quality	14
3	Water Quality.....	15
3.1	Surface Water.....	15
3.1.1	Surface Water Trigger Tracking	17
3.2	Site Water Use.....	17
3.3	HRSTS Discharge.....	17
3.4	Groundwater Monitoring Results.....	17
3.4.1	Groundwater Trigger Tracking	19
4	Blasting.....	19
4.1	Blast Monitoring Results.....	20
5	Noise.....	23
5.1	Attended Noise Monitoring Results.....	23
5.2	Low Frequency Assessment.....	26
5.3	Real Time Noise Monitoring.....	27
6	Operational Downtime.....	29
7	Rehabilitation.....	30
8	Complaints.....	31
9	Environmental Incidents.....	34

Appendix A: Meteorological Data (HVO Corporate)..... 35

Table of Figures

Figure 1 - Rainfall Summary 2024 4

Figure 2 – HVO Corporate Wind Rose for the Reporting Period 5

Figure 3 – HVO Cheshunt Wind Rose for the Reporting Period..... 5

Figure 4 – Air Quality Monitoring Location Plan 6

Figure 5 - Depositional Dust Results for the Reporting Period 7

Figure 6 – Individual PM₁₀ Results for the Reporting Period 8

Figure 7 – Year to Date Average PM₁₀ as at end of the Reporting Period 9

Figure 8 - Results for the Reporting Period..... 10

Figure 9 - Year to Date Average PM_{2.5} as at end of the Reporting Period 11

Figure 10 - Year to Date Average Total Suspended Particulates as at end of the Reporting Period 12

Figure 11 – Real Time PM₁₀ 24hr for the Reporting Period 13

Figure 12 – Real Time PM₁₀ Annual Average for the Reporting Period..... 14

Figure 13 – HVO Surface Water Monitoring Locations 16

Figure 14 - Groundwater Monitoring Locations at HVO 18

Figure 15 - Blast Monitoring Location Plan 22

Figure 16 - Noise Monitoring Location Plan 28

Figure 17 - Operational Downtime by Equipment Type for the Reporting Period 29

Figure 18 - Rehabilitation YTD November 2024 30

Table 1 - Rainfall data for the reporting period..... 4

Table 2 – Blasting Criteria 19

Table 3 – Overpressure Blast Monitoring Results for the reporting period 20

Table 4 – Ground Vibration Blast Monitoring Results for the reporting period..... 21

Table 5 - LAeq,15minute and 1minute HVO North Against Impact Assessment Criteria for the Reporting Period..... 24

Table 6 - LAeq,15minute and 1minute HVO South Against Impact Assessment Criteria for the Reporting Period..... 25

Table 7 - Modifying Factor Assessment HVO North for the Reporting Period 26

Table 8 - Modifying Factor Assessment HVO South for the Reporting Period..... 27

Table 9 - Complaints Summary 2024 31

1 | INTRODUCTION

This report has been compiled to provide a monthly summary of environmental monitoring results for Hunter Valley Operations (HVO). This report includes all monitoring data collected for the period 1 – 31 May 2024 (the ‘Reporting Period’).

2 | AIR QUALITY

2.1 | METEOROLOGICAL MONITORING

HVO maintains two meteorological stations: ‘HVO Corporate’ and ‘Cheshunt’ (refer to Figure 4).

2.1.1 | RAINFALL

Rainfall recorded at the HVO Corporate weather station during the period is summarised in Table 1. The 2021, 2022 and 2023 trends are shown in Figure 1.

Table 1 - Rainfall data for the reporting period

2024	Monthly Rainfall (mm)	Cumulative Rainfall (mm)
May	65.4	335.4




Figure 1 - Rainfall Summary 2024

2.1.2 | WIND SPEED AND DIRECTION

Figure 2 and Figure 3 wind roses show wind speeds and directions during the reporting period at HVO Corporate and Cheshunt meteorological stations respectively. South easterly winds were prevailing at HVO Corporate, whilst north west winds were prevailing at HVO Cheshunt




Figure 2 – HVO Corporate Wind Rose for the Reporting Period




Figure 3 – HVO Cheshunt Wind Rose for the Reporting Period




Figure 4 – Air Quality Monitoring Location Plan

Number: HVOOC-1797567310-4964
Owner: Superintendent - Environment and Community

Status: Approved
Version: 1.0

Effective: 19/07/2024
Review: [Planned Review Date]

2.2 | DEPOSITIONAL DUST

HVO operates and maintains a network of depositional dust gauges situated on private and mine owned land surrounding HVO to monitor regional air quality.

Figure 5 displays year-to-date (YTD) insoluble solids results from depositional dust gauges during the reporting period compared against the annual impact assessment criteria. Any monthly results deemed to be contaminated (due to presence of bird droppings, insects, etc.) are not displayed. An assessment of HVO's contribution against the long-term impact assessment criteria will be provided in the 2024 Annual Review.




Figure 5 – YTD Depositional Dust Results as at end of the Reporting Period

2.3 | SUSPENDED PARTICLES

Suspended particles are measured by a network of High Volume Air Samplers (HVAS) measuring Total Suspended Particulates (TSP) and Particulate Matter <10µm (PM₁₀). The Kilburnie South and Maison Dieu HVAS also monitor Particulate Matter <2.5µm (PM_{2.5}). The location of these monitors is presented in Figure 4. Each HVAS runs for 24-hours on a six-day cycle.

2.3.1 | HVAS PM₁₀ RESULTS

2.3.1.1 | PERFORMANCE AGAINST SHORT TERM IMPACT ASSESSMENT CRITERIA

Figure 6 shows individual PM₁₀ results at each monitoring station against the short-term impact assessment criteria of 50µg/m³ for the reporting period. All monitors were below the short-term impact assessment criteria during the reporting period.




Figure 6 – Individual PM₁₀ Results for the Reporting Period

2.3.1.2 | PERFORMANCE AGAINST LONG TERM IMPACT ASSESSMENT CRITERIA

Figure 7 shows the year-to-date annual average PM₁₀ results. All other monitors were below the relevant long term impact assessment criteria during the reporting period.

An assessment of HVO’s contribution against the long-term impact assessment criteria will be provided in the 2024 Annual Review.




Figure 7 – Year to Date Average PM₁₀ as at end of the Reporting Period

2.3.2 | HVAS PM_{2.5} RESULTS

HVO monitors PM_{2.5} at two HVAS locations, Kilburnie South and Maison Dieu.

2.3.2.1 | HVAS PM_{2.5} RESULTS

Figure 8 shows individual PM_{2.5} results at each monitoring station against the HVO South short-term impact assessment criteria of 25µg/m³ for the reporting period. Both monitors were below the relevant short-term impact assessment criteria during the reporting period.

An assessment of HVO’s contribution against the long-term impact assessment criteria will be provided in the 2024 Annual Review.




Figure 8 - Results for the Reporting Period

2.3.2.2 | PERFORMANCE AGAINST LONG TERM IMPACT ASSESSMENT CRITERIA

Figure 9 shows the year-to-date annual average PM_{2.5} results. During the reporting period, the Knodlers Lane and Warkworth monitors annual average year to date results were both above the PM_{2.5} Annual Rolling Mean criteria of 8µg/m³.

An assessment of HVO’s contribution against the long-term impact assessment criteria will be provided in the 2024 Annual Review.




Figure 9 - Year to Date Average PM_{2.5} as at end of the Reporting Period

2.3.3 | TSP RESULTS

2.3.3.1 | PERFORMANCE AGAINST LONG TERM IMPACT ASSESSMENT CRITERIA

Figure 10 shows the annual average TSP results compared against the long-term impact assessment criteria of 90µg/m³.

All monitors, except for Knodlers Lane and Warkworth, were below the relevant long-term impact assessment criteria during the reporting period.

An assessment of HVO's contribution against the long-term impact assessment criteria will be provided in the 2024 Annual Review.




Figure 10 - Year to Date Average Total Suspended Particulates as at end of the Reporting Period

2.3.4 | REAL TIME PM₁₀ RESULTS

HVO maintains a network of real time PM₁₀ monitors. The real time air quality monitoring stations continuously record information and transmit data to a central database, generating alarms when particulate matter levels exceed internal HVO trigger levels. Results from real time PM₁₀ monitoring are used as a reactive measure to guide mining operations to help achieve compliance with the relevant conditions of the project approval.

Figure 11 shows the daily 24-hour average PM₁₀ result from the real time monitoring sites. During the reporting period, daily results were below the 24-hr average criteria of 50µg/m³ with the exception of Warkworth monitor on 31 May. This exceedance was investigated internally by HVO and it was found that the maximum calculated HVO contribution was below the compliance limit.

Results were not reported for individual monitors on certain days as follows:

- Maison Dieu on 3 May due to less than 75% data capture; and
- Warkworth on 28 and 29 May due to less than 75% data capture.

Figure 12 shows the annual rolling average PM₁₀ results from the real time monitoring sites. All monitoring results were below the annual average for the relevant long-term impact assessment criteria during the reporting period, with the exception of the Warkworth monitor.




Figure 11 – Real Time PM₁₀ 24hr for the Reporting Period




Figure 12 – Real Time PM₁₀ Annual Average for the Reporting Period

2.3.5 | REAL TIME ALARMS FOR AIR QUALITY

The real time monitoring system generated sixty-two (62) automated air quality related alarms during the reporting period. Ten (10) alarms related to adverse weather conditions (wind or rain) and fifty-two (52) alarms related to dust conditions.

3 | WATER QUALITY

HVO maintains a network of surface water and groundwater monitoring sites.

3.1 | SURFACE WATER

Surface watercourses are sampled on a quarterly sampling regime. Water quality is assessed through the parameters of pH, electrical conductivity (EC) and Total Suspended Solids (TSS). The location of surface water monitoring points across HVO is shown in Figure 13.

Results from monitoring on site dams, the Hunter River and other natural tributaries are provided on a quarterly basis. Results will be provided in the June 2024 Monthly Environmental Monitoring Report.




Figure 13 – HVO Surface Water Monitoring Locations

3.1.1 | SURFACE WATER TRIGGER TRACKING

Internal trigger limits have been developed to assess monitoring data on an on-going basis and to highlight potentially adverse surface water impacts. The process for evaluating monitoring results against the internal triggers and subsequent responses are outlined in the HVO Water Management Plan.

Surface water trigger tracking results are provided on a quarterly basis. Results will be reported in the June 2024 Monthly Environmental Monitoring Report.

3.2 | SITE WATER USE

HVO is permitted to extract water from the Hunter River under water allocation licenses issued by Water NSW.

HVO did not extract water from the Hunter River during the reporting period.

3.3 | HRSTS DISCHARGE

HVO participates in the Hunter River Salinity Trading Scheme (HRSTS), allowing discharge from licensed discharge points Dam 11N (to Farrell's Creek), Lake James (to the Hunter River) and Parnell's Dam (to Parnell's Creek). Discharges can only take place subject to HRSTS regulations.

HVO did not undertake any HRSTS discharges during the reporting period.

3.4 | GROUNDWATER MONITORING RESULTS

Groundwater monitoring is undertaken on a quarterly basis in accordance with the HVO Water Management Plan and Groundwater Monitoring Programme. The location of groundwater monitoring points across HVO are show in Figure 14.

Groundwater monitoring results are provided on a quarterly basis. Results will be provided in the June 2024 Monthly Environmental Monitoring Report.




Figure 14 - Groundwater Monitoring Locations at HVO

3.4.1 | GROUNDWATER TRIGGER TRACKING

Internal trigger limits have been developed to assess monitoring data on an on-going basis and to highlight potentially adverse groundwater impacts. The process for evaluating monitoring results against the internal triggers and subsequent responses is outlined in the HVO Water Management Plan.

Groundwater trigger tracking results are provided on a quarterly basis. Results will be provided in the June 2024 Monthly Environmental Monitoring Report.

4 | BLASTING

HVO maintains a network of blast monitoring units located at nearby privately owned residences and function as regulatory compliance monitors. The location of these monitors can be found in Figure 15. Blasting criteria for HVO are summarised in Table 2.

Table 2 – Blasting Criteria

Airblast Overpressure (dBL)	Comments
115	5% of the total number of blasts in a 12-month period
120	0% of blasts
Ground Vibration (mm/s)	Comments
5	5% of the total number of blasts in a 12-month period
10	0% of blasts



4.1 | BLAST MONITORING RESULTS

Seventeen (17) blasts were initiated at HVO during the reporting period. Blast monitoring results for the period are shown in Table 3 and Table 4.

Table 3 – Overpressure Blast Monitoring Results for the reporting period

Date and Time	Moses Crossing (dBL)	Jerrys Plains Village (dBL)	Maison Dieu (dBL)	Warkworth (dBL)	Knodlers Lane (dBL)
1/05/2024 16:01	93.11	92.49	98.27	95.62	93.11
4/05/2024 12:57	102.56	103.93	94.56	83.53	102.56
4/05/2024 14:28	100.55	99.32	90.49	99.14	100.55
8/05/2024 13:15	97.72	91.28	96.00	88.94	97.72
10/05/2024 16:08	96.88	96.32	92.25	87.15	96.88
11/05/2024 13:05	101.76	93.72	96.14	88.31	101.76
11/05/2024 16:15	97.91	94.48	86.23	90.20	97.91
13/05/2024 10:33	96.01	100.15	94.60	90.50	96.01
17/05/2024 16:59	87.61	80.59	87.60	89.97	87.61
17/05/2024 17:10	88.47	81.24	93.37	91.09	88.47
20/05/2024 13:00	93.40	89.00	104.64	98.29	93.40
21/05/2024 13:02	100.72	94.10	97.91	98.24	100.72
22/05/2024 16:04	80.84	76.34	81.13	92.52	80.84
23/05/2024 13:09	103.96	105.17	95.67	90.41	103.96
24/05/2024 13:04	91.87	83.99	99.88	96.17	91.87
25/05/2024 16:42	82.80	87.03	81.00	97.52	82.80
30/05/2024 13:07	91.26	87.78	93.90	89.25	91.26



Table 4 – Ground Vibration Blast Monitoring Results for the reporting period

Date and Time	Moses Crossing (mm/s)	Jerrys Plains Village (mm/s)	Maison Dieu (mm/s)	Warkworth (mm/s)	Knodlers Lane (mm/s)
1/05/2024 16:01	0.11	0.18	0.07	0.06	0.11
4/05/2024 12:57	0.16	0.12	0.08	0.31	0.16
4/05/2024 14:28	0.10	0.04	0.05	0.30	0.10
8/05/2024 13:15	0.10	0.05	0.09	0.24	0.10
10/05/2024 16:08	0.09	0.06	0.08	0.14	0.09
11/05/2024 13:05	0.10	0.03	0.03	0.07	0.10
11/05/2024 16:15	0.13	0.13	0.30	0.11	0.13
13/05/2024 10:33	0.27	0.11	0.28	0.86	0.27
17/05/2024 16:59	0.07	0.03	0.06	0.43	0.07
17/05/2024 17:10	0.09	0.03	0.06	0.73	0.09
20/05/2024 13:00	0.09	0.04	0.07	0.24	0.09
21/05/2024 13:02	0.14	0.07	0.11	0.18	0.14
22/05/2024 16:04	0.08	0.04	0.06	0.03	0.08
23/05/2024 13:09	0.15	0.04	0.07	0.31	0.15
24/05/2024 13:04	0.26	0.09	0.15	0.28	0.26
25/05/2024 16:42	0.22	0.11	0.49	1.40	0.22
30/05/2024 13:07	0.12	0.04	0.07	0.30	0.12




Figure 15 - Blast Monitoring Location Plan

Number: HVOOC-1797567310-4964
Owner: Superintendent - Environment and Community

Status: Approved
Version: 1.0

Effective: 19/07/2024
Review: [Planned Review Date]



5 | NOISE

Routine attended noise monitoring occurs at defined locations around HVO, as described in the HVO Noise Monitoring Programme. The noise monitoring aims to quantify and describe the acoustic environment around the site and compare results with specified limits. The attended noise monitoring locations are displayed in Figure 16.

5.1 | ATTENDED NOISE MONITORING RESULTS

Attended monitoring was conducted at receiver locations around HVO during the night period of 1 May 2024.

Compliance with the HVO noise impact limits ensures compliance with the land acquisition criteria. Therefore, since no noise impact exceedances occurred for the reporting period the land acquisition assessment has not been presented. These will only be reported in instances of noise impact exceedances.

Monitoring results are detailed in Table 5 and Table 6.



Table 5 - LAeq,15minute and 1minute HVO North Against Impact Assessment Criteria for the Reporting Period

Location	Start date and time	Wind		Stability class	Very enhancing? ¹	HVO North limits, dB ¹		HVO North levels, dB		Exceedances, dB	
		Speed m/s	Direction ³			L _{Aeq,15minute}	L _{A1,1min}	L _{Aeq,15minute} ²	L _{A1,1min}	L _{Aeq,15minute}	L _{A1,1min}
Shearers Lane	1/05/2024 21:00	3.8	177	D	No	35	46	IA	IA	N/A	N/A
Knodlers Lane	1/05/2024 21:50	4.6	175	D	No	35	46	IA	IA	N/A	N/A
Maison Dieu	1/05/2024 21:25	4.4	173	D	No	35	46	IA	IA	N/A	N/A
Long Point (Dights Crossing)	1/05/2024 22:49	2.5	168	D	Yes	35	46	IA	IA	Nil	Nil
Kilburnie South	1/05/2024 23:10	3.1	171	D	No	39	46	IA	IA	N/A	N/A
Jerrys Plains East	1/05/2024 22:50	2.5	168	D	Yes	39	46	IA	IA	Nil	Nil
Jerrys Plains Village	1/05/2024 21:19	3.8	179	D	No	40	46	IA	IA	N/A	N/A
Jerrys Plains West	1/05/2024 21:00	3.8	177	D	No	40	46	IA	IA	N/A	N/A

- Noise limits are adjusted by +5 dB during 'very noise-enhancing meteorological conditions' in accordance with the NPfl.
- Site-only LAeq,15minute, includes modifying factor penalties if applicable.
- Degrees magnetic north, "-" indicates calm conditions.

Number: HVOOC-1797567310-4964

Status: Approved

Effective: 19/07/2024

Owner: Superintendent - Environment and Community

Version: 1.0

Review: [Planned Review Date]

Table 6 - LAeq,15minute and 1minute HVO South Against Impact Assessment Criteria for the Reporting Period

Location	Start date and time	Wind		Stability class	Very enhancing? ¹	HVO South limits, dB ¹		HVO South levels, dB		Exceedances, dB	
		Speed m/s	Direction ³			LAeq,15minute	LA1,1min	LAeq,15minute ²	LA1,1min	LAeq,15minute	LA1,1min
Shearers Lane	1/05/2024 21:00	3.7	157	D	No	41	45	NM	NM	N/A	N/A
Knodlers Lane	1/05/2024 21:50	3.2	150	D	No	40	45	IA	IA	N/A	N/A
Maison Dieu	1/05/2024 21:25	2.8	156	D	Yes	39	45	IA	IA	Nil	Nil
Long Point (Dights Crossing)	1/05/2024 22:49	2.3	160	D	Yes	37	45	IA	IA	Nil	Nil
Kilburnie South	1/05/2024 23:10	3.3	150	D	No	39	45	IA	IA	N/A	N/A
Jerrys Plains East	1/05/2024 22:50	2.3	160	D	Yes	38	45	IA	IA	Nil	Nil
Jerrys Plains Village	1/05/2024 21:19	2.8	167	D	Yes	35	45	IA	IA	Nil	Nil
Jerrys Plains West	1/05/2024 21:00	3.7	157	D	No	35	45	IA	IA	N/A	N/A
HVGC	1/05/2024 23:37	3.4	157	D	No	55	--	IA	IA	N/A	N/A

- Noise limits are adjusted by +5 dB during 'very noise-enhancing meteorological conditions' in accordance with the NPf.
- Site-only LAeq,15minute, includes modifying factor penalties if applicable.
- Degrees magnetic north, "--" indicates calm conditions.
- NM = Not Measurable

Number: HVOOC-1797567310-4964

Status: Approved

Effective: 19/07/2024

Page 25 of 35

Owner: Superintendent - Environment and Community

Version: 1.0

Review: [Planned Review Date]

Uncontrolled when printed

5.2 | LOW FREQUENCY ASSESSMENT

In accordance with the requirements of the EPA's Noise Policy for Industry (NPfl), the applicability of the low frequency modification penalty has been assessed. No penalties were applied for monitoring undertaken through the reporting period. The assessments for the low frequency noise are shown in Table 7 and Table 8.

Table 7 - Modifying Factor Assessment HVO North for the Reporting Period

Location	Start date and time	Measured HVO South L_{Aeq} dB	Very enhancing? ¹	Intermittency modifying factor?	Tonality modifying factor?	Frequency of tonality	Low-frequency modifying factor? ^{1,2}	Exceedance of reference spectrum ^{2,3}	Total penalty dB ^{2,3}
Shearers Lane	1/05/2024 21:00	NM	No	N/A	N/A	N/A	N/A	N/A	N/A
Knodlers Lane	1/05/2024 21:50	IA	No	N/A	N/A	N/A	N/A	N/A	N/A
Maison Dieu	1/05/2024 21:25	IA	No	N/A	N/A	N/A	N/A	N/A	N/A
Long Point (Dights Crossing)	1/05/2024 22:49	IA	Yes	No	No	N/A	No	N/A	No
Kilburnie South	1/05/2024 23:10	IA	No	N/A	N/A	N/A	N/A	N/A	N/A
Jerrys Plains East	1/05/2024 22:50	IA	Yes	No	No	N/A	No	N/A	No
Jerrys Plains Village	1/05/2024 21:19	IA	No	N/A	N/A	N/A	N/A	N/A	N/A
Jerrys Plains West	1/05/2024 21:00	IA	No	N/A	N/A	N/A	N/A	N/A	N/A

1. Low-frequency modifying factors are not applicable during 'very noise-enhancing meteorological conditions' in accordance with the NPfl.

2. NA denotes 'not applicable'.

3. Bold results indicate that application of NPfl modifying factor(s) is required.

Table 8 - Modifying Factor Assessment HVO South for the Reporting Period

Location	Start date and time	Measured HVO South LAeq dB	Very enhancing? ¹	Intermittency modifying factor?	Tonality modifying factor?	Frequency of tonality	Low-frequency modifying factor? ^{1,2}	Exceedance of reference spectrum ^{2,3}	Total penalty dB ^{2,3}
Shearers Lane	1/05/2024 21:00	IA	No	N/A	N/A	N/A	N/A	N/A	N/A
Knodlers Lane	1/05/2024 21:50	IA	No	N/A	N/A	N/A	N/A	N/A	N/A
Maison Dieu	1/05/2024 21:25	IA	Yes	N/A	N/A	N/A	N/A	N/A	N/A
Long Point (Dights Crossing)	1/05/2024 22:49	IA	Yes	Nil	No	N/A	No	N/A	Nil
Kilburnie South	1/05/2024 23:10	IA	No	N/A	N/A	N/A	N/A	N/A	N/A
Jerrys Plains East	1/05/2024 22:50	IA	Yes	Nil	No	N/A	No	N/A	Nil
Jerrys Plains Village	1/05/2024 21:19	IA	Yes	N/A	N/A	N/A	N/A	N/A	N/A
Jerrys Plains West	1/05/2024 21:00	IA	No	N/A	N/A	N/A	N/A	N/A	N/A
HVGC	1/05/2024 23:37	NM	No	N/A	N/A	N/A	N/A	N/A	N/A

1. NA denotes 'not applicable'

2. NM denotes 'not measurable'

3. Bold results indicate that application of NPfl modifying factor/s is required

5.3 | REAL TIME NOISE MONITORING

HVO utilises a network of real-time directional noise monitors to manage noise impacts on a continuous basis, shown in Figure 16. Noise alarms are in place at five monitoring locations (Knodlers Lane, Maison Dieu, Jerrys Plains, Moses Crossing, and Long Point) which alert HVO staff to elevated noise levels that require investigation.

HVO investigates and responds to noise alarms with appropriate modification to operations. Changes in response to a noise alarm can include replacing equipment with alternative units, changing or relocating tasks, or shutting down equipment. It should be noted that this assessment does not compliment or conflict with attended noise monitoring detailed in **Section 5.1** |. Real time monitoring data includes non-mine noise sources such as animals, road traffic and weather.




Figure 16 - Noise Monitoring Location Plan

Number: HVOOC-1797567310-4964
Owner: Superintendent - Environment and Community

Status: Approved
Version: 1.0

Effective: 19/07/2024
Review: [Planned Review Date]

6 | OPERATIONAL DOWNTIME

A total of thirty-nine (39) hours of equipment downtime was logged in response to real time monitoring and inspections for environmental factors such as noise and dust during the reporting period. Operational downtime by equipment type is show in Figure 17. Note that these delays are instances where operations were completely stopped and does not include occasions where operations were changed/modified but not stopped (e.g. changed from exposed dump to in-pit dump).




Figure 17 - Operational Downtime by Equipment Type for the Reporting Period

7 | REHABILITATION

The following activities related to rehabilitation were completed during the reporting period:

- 3.66ha of land was reshaped;
- 3.66ha of land was released (became available for the application of topsoil);
- 9.86ha of land was topsoiled; and
- 0.72ha of land was rehabilitated.

Year to date progress is shown in Figure 18.




Figure 18 - Rehabilitation YTD February 2024

8 | COMPLAINTS

There was one (1) complaint received during the reporting period. Details of complaints received during 2024 are shown in Table 9.

Table 9 - Complaints Summary 2024

Complaint Number	Date	Time	Complainant ID	Nature of Complaint	Mode of Complaint	Brief Description and Response
No community complaints were received during January						
No community complaints were received during February						
1	12 March	8:59pm	1	Noise	Community Hotline	<ul style="list-style-type: none"> A resident of Jerrys Plains called the Community Complaints Hotline at 8:59pm regarding noise, commenting that “noise is pretty loud tonight” as well as equipment horns could be heard. The OCE on duty in South Pit contacted the resident at 9:02pm and subsequently notified the OCE on duty in West Pit. Following communication between West Pit OCE and relevant equipment operators, horn blasting and dumping practices – thought to be the causes of the disturbance – were altered and/or stopped. An internal investigation conducted following the complaint found that no noise alarms had triggered within one hour of the complaint. Horn noise was audible from noise recordings at the Jerrys Plains noise monitor.
2	2 April	1:31pm	2	Blast	Community Hotline	<ul style="list-style-type: none"> A resident of Jerrys Plains called the United Wambo Joint Venture (UWJV) Community Complaints Hotline at 1:31pm regarding noise and vibration from a blast. This was relayed to HVO given they did not have a blast at that time.

Number: HVOOC-1797567310-4964

Status: Approved

Effective: 19/07/2024

Page 31 of 35

Owner: Superintendent - Environment and Community

Version: 1.0

Review: [Planned Review Date]

Uncontrolled when printed

Complaint Number	Date	Time	Complainant ID	Nature of Complaint	Mode of Complaint	Brief Description and Response
						<ul style="list-style-type: none"> A member of the HVO Environment and Community team contacted the resident to advise a blast had been fired in the Mitchell Pit at 1:29pm. The closest monitor to the resident recorded overpressure of 105.5 dBL against a criteria of 120 dBL and ground vibration of 0.11mm/s against a criteria of 10mm/s.
3	4 April	12:30pm	3	Traffic	Community Hotline	<ul style="list-style-type: none"> A resident of Jerrys Plains called the Community Complaints Hotline at 12:30pm regarding traffic incidents at HVO North entry off Lemington Road. The resident reported that a vehicle exiting HVO North on the afternoon of 3 April failed to stop at the stop sign and almost collided with his wifes vehicle. They have witnessed other vehicles failing to stop at the same location within the past two months. An internal investigation following the complaint resulted in a site-wide presentation about the importance of road safety whilst travelling to and from HVO delivered at daily HCOMs. Vegetation maintenance will be performed to increase visibility at the intersection.
4	3 May	7:40am	3	Traffic	Direct call to Environment and Community Officer	<ul style="list-style-type: none"> A resident of Jerrys Plains called the Environment and Community Officer directly regarding a traffic incident at HVO North's intersection with Lemington Road. The resident reported that a vehicle (small truck) exiting HVO North at approximately 7:40am on 3 May failed to stop at the stop sign and almost collided with his wifes vehicle. Following an internal investigation into the complaint, a site-wide communication about road safety and the 100km/h speed limit along Lemington Road was delivered at daily HCOMs. In

Number: HVOOC-1797567310-4964

Status: Approved

Effective: 19/07/2024

Page 32 of 35

Owner: Superintendent - Environment and Community

Version: 1.0

Review: [Planned Review Date]

Uncontrolled when printed



REPORT | MONTHLY ENVIRONMENTAL MONITORING REPORT MAY 2024

Complaint Number	Date	Time	Complainant ID	Nature of Complaint	Mode of Complaint	Brief Description and Response
						addition, road marking, signs and the surveillance camera near the intersection will be upgraded.

Number: HVOOC-1797567310-4964

Status: Approved

Effective: 19/07/2024

Owner: Superintendent - Environment and Community

Version: 1.0

Review: [Planned Review Date]

9 | ENVIRONMENTAL INCIDENTS

There was one (1) reportable environmental incident during the reporting period. A summary of this incident is provided below.

5/05/2024 – Long Point HVAS PM₁₀ mis-capture

HVO were notified by the environmental monitoring contractor that the Long Point PM₁₀ HVAS failed to run for the full monitoring period on 5 May 2024 due to a suspected power supply failure. The monitoring contractor collecting the filter paper following the run day noted that the unit was without power upon their arrival due to the residual current device (RCD) being in the 'off' position. HVO engaged an electrician to investigate the power supply at the site, of which no issues or causes of the power supply failure were identified. As a precaution, the electrician replaced the RCD given this issue has occurred twice within four weeks. The monitoring unit was reset and successfully collected subsequent samples. The Department of Planning Housing and Infrastructure (DPHI) were notified of the mis-capture.



APPENDIX A: METEOROLOGICAL DATA (HVO CORPORATE)

Date	Air Temp Max (°C)	Air Temp Min (°C)	Relative Humidity (Max %)	Relative Humidity (Min %)	Solar Radiation Maximum (W/Sq. M)	Average Wind Direction (°)	Average Wind Speed (m/sec)	Rainfall (mm)
1/05/2024	16.27	10.94	94.20	69.66	710	131	2.22	7.0
2/05/2024	18.04	11.30	89.40	58.10	535	117	2.07	0.0
3/05/2024	19.31	9.30	94.80	52.87	929	140	2.10	0.2
4/05/2024	19.03	10.57	94.90	62.40	1086	112	2.06	8.4
5/05/2024	17.98	11.35	95.30	67.98	877	134	1.50	4.8
6/05/2024	16.32	11.37	95.40	80.90	719	125	2.86	19.8
7/05/2024	18.81	9.35	92.40	56.32	1005	111	2.06	0.2
8/05/2024	20.02	10.48	94.40	55.25	930	120	1.75	0.0
9/05/2024	20.17	11.16	94.50	59.99	930	113	2.07	0.0
10/05/2024	18.61	12.11	92.30	64.25	853	121	2.17	0.0
11/05/2024	16.41	12.43	96.30	84.00	557	123	2.39	17.2
12/05/2024	19.83	12.17	95.50	57.63	977	197	0.73	1.2
13/05/2024	20.11	12.03	92.50	61.33	1025	254	1.95	0.0
14/05/2024	22.34	10.64	94.40	41.08	623	221	1.34	0.2
15/05/2024	21.74	11.25	92.90	40.42	639	216	0.51	0.2
16/05/2024	20.26	10.11	95.90	50.35	667	137	1.04	0.0
17/05/2024	20.20	10.94	95.80	55.01	834	286	1.81	0.0
18/05/2024	14.36	8.72	87.10	56.62	631	178	2.31	0.4
19/05/2024	17.44	7.62	76.77	41.43	812	254	1.41	0.0
20/05/2024	16.79	5.94	71.58	37.79	719	218	1.70	0.0
21/05/2024	17.64	10.12	91.10	54.96	922	132	1.01	0.0
22/05/2024	18.65	7.42	91.30	46.24	598	222	0.96	0.0
23/05/2024	18.54	5.88	93.30	46.85	883	193	0.79	0.0
24/05/2024	19.61	6.67	94.00	52.66	679	191	0.71	0.0
25/05/2024	17.82	7.74	95.50	62.51	771	151	0.84	0.0
26/05/2024	19.95	9.81	94.60	54.74	671	283	1.24	0.2
27/05/2024	20.92	8.53	92.00	41.81	679	237	1.75	0.0
28/05/2024	20.55	7.02	95.00	41.05	516	206	0.77	0.0
29/05/2024	22.89	6.44	92.30	36.85	509	243	0.93	0.2
30/05/2024	22.34	8.81	89.80	42.82	515	228	1.31	0.0
31/05/2024	21.64	13.34	93.30	48.34	636	287	3.29	3.8